

## PROCESS / PRODUCT CHANGE NOTIFICATION

### PCN1801

#### 1. Products affected

UFC100-L1                      order number: IFL-KK-020901

#### 2. Description of change

The UFC100-L2 will be manufactured by a different foundry.  
New order number of UFC100-L2: IFL-KK-020911

#### 3. Reason of change

This is to protect against the end of life from the current foundry and to extend the life of the product for 5 – 10 years.

UFC100-L2 has function, package and pins same as UFC100-L1, except in „L2“ the following pins are not 5 V tolerant.

Pin	Signal
7	RESETn
21	RxS
22	RxA
26	FLT0n
37	CTYP
38	ATYP

UFC100-L2 draws lower current – approx. 60% of „L1“ from the power supply.

#### 4. Recommended actions

Milestones	Dates (Year-Month-Day)
Last date to acknowledge receipt of this notification*	
Last date to request additional information or clarification	2018-07-02

\* Note, in accordance with JESD46D, this change is deemed acceptable if no response or acknowledgement is received within 30 days from the date of this notification.

5. Product Transition Dates

<b>Milestones</b>	<b>Dates (Year-Month-Day)</b>
Last date of acknowledgement and samples order	2018-07-02
Qualification samples available	2018-08-01
Last date for ordering unchanged product (UFC100-L1)	2019-01-01
First date of shipment of changed product (UFC100-L2)	2019-01-01
Last shipping date of unchanged product	2019-12-30

6. Support Contact

For more information, please contact Softing Technical Support by submitting a Service Request at Softing's Support website.

<http://industrial.softing.com/en/about-us/contact.html>